






HELIAX® Cable	EZfit® Connectors	Universal Hand Prep Tool	Drill Tool for HELIAX Smoothwall AL	Drill Tool for HELIAX Corrugated CU	Wrenches: Back Nut/ Front Nut
1/2" Superflexible					
SFX-500 HELIAX Smoothwall AL	SFX A-Series SFX-ADM SFX-ADF SFX-ANM SFX-ANF SFX-ADMR SFX-ANMR 	Hand Prep Tool not available for SFX-500.	SFX-EZPT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For SFX-500 cable only. Supplied with T-handle for hand use. 	1/2" HELIAX CU cable and drill tool not available	EZW-7812 Combination Wrench  TW-SFX-EZFC Torque Wrench 
1/2"					
FXL-540 HELIAX Smoothwall AL LDF4-50A HELIAX Corrugated CU	540EZDMV2*, 540EZDFV2*, 540EZNMV2*, 540EZNFV2*, 540EZDMRV2*, 540EZNMRV2*, L4TDM-PSA, L4TDF-PSA, L4TNM-PSA, L4TNF-PSA 	12-HPT The 1/2 inch hand prep tool removes jacketing, cores foam and flares sheath for easy connector attachment. Includes bits for FXL-540 cables. Drill not required. 	540-EZPT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For FXL-540 cable only. Supplied with T-handle for hand use. 	Drill driven tool not available for LDF4-50A 1/2" cable.	EZW-7812 Combination Wrench  TW-12-EZFC Torque Wrench 
7/8"					
FXL-780 HELIAX Smoothwall AL AVA5-50 HELIAX Corrugated CU	78 EZfit® Series: 78EZDF 78EZDM 78EZN 78EZN 	78-HPT The 7/8 inch hand prep tool removes jacketing, cores foam and flares sheath for easy connector attachment. Includes bits for FXL-780 and AVA5 series cables. Drill not required. 	780-EZPT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For FXL-780 cable only. Supplied with T-handle for hand use. 	A5-EZPT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For AVA5 cable only. Supplied with T-handle for hand use. 	EZW-7812 Combination Wrench  TW-78-EZFC Torque Wrench 
1-1/4"					
FXL-1480 HELIAX Smoothwall AL AVA6-50 HELIAX Corrugated CU	114 EZfit® Series: 114EZDF 114EZDM 114EZN 114EZN 	Hand prep tool not available for 1-1/4" cable.	1480-PT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For FXL-1480 cable only. Supplied with T-handle for hand use. 	A6-EZPT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For AVA6 cable only. Supplied with T-handle for hand use. 	TW-114-EZFC Torque Wrench 
1-5/8"					
FXL-1873 HELIAX Smoothwall AL AVA7-50 HELIAX Corrugated CU	158 EZfit® Series: 158EZDF 158EZDM 158EZN 158EZN 	Hand prep tool not available for 1-5/8" cable.	FXL/CR 1873-PT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For FXL-1873 cable only. Supplied with T-handle for hand use. 	A7-EZPT Drill driven tool removes jacketing, cores foam and flares sheath. Speeds connector attachment. For AVA7 cable only. Supplied with T-handle for hand use. 	1873-AW 2-3/8" (60 mm) Wrench  TW-158-EZFC Torque Wrench 